



Figure 3 – Vestry showing access opening-up holes.



Figure 4 – Vestry Ceiling showing crack and bulge.



*Figure 5 – Roof void below drip showing wet area at bottom of noggin and new timbers supporting a recent ceiling repair.*



*Figure 6 – Vestry Roof Covering. Central section covered in bitumen. The roof pitch is very shallow and there was a lot of standing water.*



Figure 7 – Showing drip with Westwood PMMA waterproofing system applied in November 2023.



Figure 8 – Detail of above.



*Figure 9 – North Aisle gutter discharging onto vestry roof.*